STATE	COUNTY	TOWN OR VICINITY	
North		2ρ	
Carolina	Gates	Gates vicinity d	
INDEX NUMBER	MONUMENT		
NC, 37- GAT.V , 2	VLittle Ri	iddick House	
REPRESENTED IN NEGATIVE FILE	H.A.B.S. SURVEY NO.	Owner: Mrs. Hubert Eason	
PUBLISHED PHOTOGRAPHS		Date of erection: unknown; may be late 17 or early 18th century Present condition: abandoned Description: Frame; one story and loft; gable roof; inside end chimney, now destroyed.	
PUBLISHED DRAWINGS	Description		
	Plan: one north; bes	Plan: one room, center door each wall except north; beamed ceiling; framing shows chimney location and indicates small room or closet to west with 4/4 double-hung window	
ero 6—8369	10-444 HIS	TORIC AMERICAN BUILDINGS SURVEY	

(now missing) and space for ladder to loft at east of chimney. Doors heavily studded with wrought-iron spikes in diagonal pattern; chisel marks forming pattern can still be seen in places; doors vertically sheathed on exterior and horizontally on interior.

Prepared by Thomas T- Waterman 1940